


LASER®

C-Frame Socket Press

Instructions



Ref.	Description	Qty
A	Frame	1
B	Forcing Screw	1
C	Anvil-Fixed - 1/4"	1
D	Anvil-Fixed - 3/8"	1
E	Anvil-Fixed - 1/2"	1

Ref.	Description	Qty
F	Anvil-Rotating - 1/4"	1
G	Anvil-Rotating - 3/8"	1
H	Anvil-Rotating - 1/2"	1
I	Anvil-Fixed - Flat	1
J	Anvil-Rotating - Flat	1

LASER[®]

C-Frame Socket Press

Instructions



Before:



After:



IMPORTANT: ensure the force screw is well lubricated with molybdenum disulphide grease before use.