

Temperature/Humidity Level Meter

Temperature and humidity meter, with data hold function, auto backlight and auto power-off.



Additional Information

- Temperature range: -10° to +50°C / 14° to 122°F (accuracy +/- 1°C).
- Humidity: 10% to 99%.
- · 9V battery included.
- CE, UKCA & RoHS compliant.

http://lasertools.co.uk/product/6904

LASER Kamasa Gunson Connect









