

## Oxygen Sensor Boss Thread Repair Kit M18

Designed for the repair of damaged Lambda (oxygen) sensors threads.



### Additional Information

- Set includes: 5 x thread repair inserts M18 x 1.5.
- M18 x 1.5 taper tap & M20 x 1.5 taper tap.
- Reamer & insert tool.
- Spares insert nuts available, please see Laser Part No. 0069 (pack of 5).
- 

<http://lasertools.co.uk/product/5476>

