

## Zestaw do wyciągania balansera - BMW

The 7253 is made up of the tools required to remove, replace and time the balance shaft on the BMW 1.5 diesel, 1.2 & 1.5 petrol engines. Laser recommend the use of the Laser 6997 timing tool kit and Laser 7067 split gear alignment tool when refitting the balance shaft split gear. NOTE: the use of 7253 requires the use of a copper mallet to drive out the balance shaft. Wear protective gloves and eye protection at all times during use.



### Additional Information

- Zastosowanie: Mini Clubman od 2015 do 2017, Mini cabrio od 2016 do 2017, Mini Clubman od 2015 do 2017, BMW 1&3 od 2015 do 2017, BMW 2 od 2014 do 2017, BMW X1 od 2015 do 2017, BMW i8 od 2015 do 2017
- Kody silników B37 Diesel, B38 benzyna
- Odpowiednik OEM 2 288 943, 2 288 942 & 2 358 646 (używany z narzędziem wyrównującym 7067).
- Do rozrządu silnika B37 Diesel użyj narzędzia Laser nr 6997, a do B38 benzyna narzędzia Laser nr 7242.
- Made in Sheffield. Tylne płyta jest wzorem zarejestrowanym w UE.

<http://lasertools.co.uk/product/7253>

