

Verschleißanzeige für Nockenwellentriebsketten

The 7034 Camshaft Drive Chain Wear Indicator allows the user to check the timing chain stretch on BMW MINI petrol engines without dismantling the engine. An essential diagnostic tool that can save significant time and cost. The 7034 is made up of 5 individual working components that are manufactured to work together to give a repeatable result every time. The need for close tolerances with minimum friction does make this tool appear to be expensive but the saving in time it can give in diagnosing and confirming chain wear issues can more than justify this expense. The 7034 comes ready assembled and will not need to be adjusted or disassembled.



Additional Information

- Einsatzmöglichkeit: Mini Clubman, Clubvan, Countryman, Coupé, Mini, Paceman und Roadster, 1,4- und 1,6-l-Motoren.
- Entspricht OEM 2 353 281
- Dient zur Messung der Kettendehnung ohne Demontage des gesamten Motors. Auch für einige PSA-Motoren nützlich.
- Motorcodes: N12 B14AB, N12 B14, N12 816A, N16 816A, N16 816MO, N16 B16UO, N16 816A/MO, N16816KO, N18 816A, N18 816A/MO, N18B16C, N18B16A/MO, N18, N18 B16MO, N18 816C/TO
- Hergestellt in Sheffield

<http://lasertools.co.uk/product/7034>

